

## **Milan / Paylink Firmware Version 4.1.12.72 Release Notice.**

This is a **Full** (4) release of the Milan / Paylink Interface firmware - code version **1.12.72**.

This release note covers only the differences from **4.1.12.7**.

### ***Specific bugs fixed.***

The following significant bug was present in the release version of 4.1.12.7

- All inputs had their logical sense inverted.

### ***Specific Updates.***

- This release caters for the update to the F53 dispenser for the new IK £5 note.
- The GEN2 printer handler now tries 19.2K and 9600 baud connections.

### ***General bugs fixed.***

The following significant bugs were present in the release version of 4.1.12.7 and all earlier versions of Paylink

- The CR105 / BCR error / abnormal situation handling was improved.
- The NV200 handling of certain abnormal situations has been rewritten.
- A name clash from the AESInhei.h header file has been resolved.
- The MDB bill acceptor now updates a fixed disconnection when disabled
- Bug in Fault detect for multi note escrow is cleared
- Bug fix for extended escrow on USB connected devices
- Bug fix for power loss during bill dump on an SCR recycler.