

Milan / Paylink Firmware Version 4.1.12.81 Release Notice.

This is a **Full** (4) release of the Milan / Paylink PC Software - code version **1.12.81**.

Release **4.1.12.81** is an update **only** to the PC support software, for two significant updates. The code in an external Paylink remains unchanged, only those people affected by the two problems below need to use this update.

Specific Fixes.

- Using an external Paylink together with USB peripherals had a major bug in the handling of the external Paylink unit being power cycled / reset. Installations with USBN peripherals and an external Paylink unit should upgrade to this version of Paylink.exe
- The MEI BNR code would apply a timeout to the bill dump process that was inappropriate. Paylink no longer puts any requirements on the time taken to perform a dump.