

## **Milan / Paylink Firmware Version 2.1.12.51 Release Notice.**

This is an emergency release of the Milan / Paylink Interface firmware code version **1.12.5**.

The released code had a major fault in the dispenser ordering that renders it liable to only use one dispenser for all dispense operations.

The firmware version **2.1.12.51** is otherwise identical to **2.1.12.5** except for this one bug fix.

Note that this bug is also in the USB peripheral version, and so this emergency release also contains version **2.1.12.51** of the Paylink.exe driver program.