

Milan / Paylink Firmware Version 4.1.10.7 Release Notice.

This is a **Full** (4) release of the Milan / Paylink Interface firmware - code version **1.10.7**

This release is purely a minor bug fix from release 1.10.6.

PC code versions.

No new PC code is associated with this release

Significant Side effects from version 1.10.6

None

Bug fixes from version 1.10.6

- Revised handling of escrow commands, to remove bugs in barcode / note interaction.
- Update to the ID-003 handler to only issue disable commands when the acceptor is idle

Compatibility with 1.10.6

All software in this release can be freely mixed with that in 1.10.6.

Upgrade / Downgrades

Any earlier version of the firmware can be upgraded to this version without any problems.

Downgrading to 1.10.6 or 1.9.x will not cause any problem