

Milan / Paylink Firmware Version 4.1.10.41 Release Notice.

This is a **Full** (4) release of the Milan / Paylink Interface firmware - code version **1.10.41**.

This release increases the resilience of the inhibits on ID-003 and cctalk note acceptors.

This release is an upgrade to 1.10.4. All changes are referenced to the FULL (4) distribution of the 1.10.4 firmware and associated PC support files.

The main features of this release as compared with 1.10.4 are:

- ? Notes read into Escrow are checked against the current inhibit settings, and are returned if they should be inhibited.

Significant Side effects from version 1.10.4

- ? None

Upgrade / Downgrades

Any earlier version of the firmware can be upgraded to this version without any problems.

Due to residual data in the E²Prom, downgrading from this version to other versions may or may not work; the only guaranteed downgrade path is to version x. 1.9.x.